



**Barriers to Passage**

There were few definitively identified barriers to passage. Many culverts however were either undersized and/or actively failing. These culverts should be considered significant impediments to passage, and as a whole they may be restricting salmonid distribution. At a watershed scale, Stimson Lumber has expended significant resources to replace undersized, poorly placed, and failing culverts within their management boundary. Almost no barriers to passage occur on private forestry ownership. For comprehensive culvert results refer to appendix A.



Map 6 - Passage Barriers